



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
STONECROFT ROAD	O/S 25-27	Dangerous	Buttress roots encroaching f/w and stem within c/w - vehicle struck	Sorbus aucuparia sp	Plant in verge centrally o/s 25-27 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
STONECROFT ROAD	O/S 37-39	Dangerous	Basal decay, structural integrity in doubt	Sorbus aucuparia sp	Plant in verge centrally o/s 37-39 (same position as felled tree)	Crataegus laevigata 'Paul's Sc
STONECROFT ROAD	Side of 44 Marstone Cres, tree on STONECROFT RD	Dangerous	Basal cavity/decay, structural integrity in doubt	Malus sp	Plant in verge centrally at SIDE OF 44 Marstone Cres (same position as felled tree)	Crataegus laevigata 'Paul's Sc
STONECROFT ROAD	Side of 42 Marstone Cres, tree on STONECROFT RD	Dangerous	Multiple stem wounds, poor specimen	Prunus Kanzan	Plant in verge centrally at SIDE OF 42 Marstone Cres (same position as felled tree)	Crataegus laevigata 'Paul's Sc
STONECROFT ROAD	verge o/s 1	Dangerous	ganoderma decay of buttress root	Prunus Kanzan	verge o/s 1	crataegus pauls scarlett